LEGEND:

FIBERS SITE BOUNDARY

**FENCE** 

ROAD

ELECTRIC POLE

LAMP POLE

----- SWALE

++++++ RAILROAD TRACKS

DIRT ROAD

- GROUNDWATER MONITOR WELL
- GROUNDWATER EXTRACTION WELL
- GROUNDWATER MONITOR CLUSTER WELL
- GROUNDWATER PRODUCTION WELL
- GROUNDWATER PRODUCTION WELL NOT IN USE

HALOETHER 508 ISOCONTOUR WITH GROUNDWATER CONCENTRATION (MICROGRAMS PER LITER [µg/L]) DASHED WHERE INFERRED

26.4 HALOETHER 508 GROUNDWATER CONCENTRATION (µg/L)

CONCENTRATION EXCEEDS GROUNDWATER CLEANUP CRITERIA (GWCC) OF 50 µg/L

THE ANALYTE WAS ANALYZED FOR BUT NOT DETECTED AT THE REPORTING LIMIT OR METHOD DETECTION LIMIT INDICATED

NOT SAMPLED

PR-3 PUERTO RICO HIGHWAY 3

FIBERS PUBLIC SUPPLY WELLS SUPERFUND SITE GUAYAMA, PUERTO RICO SECOND SEMI-ANNUAL GROUNDWATER

**MONITORING REPORT FOR 2016** 

**HALOETHER 508 ISOPLETH MAP** (MARCH-MAY 2015)



**FIGURE** C-10